


NOTE: 5 WINDOWS SPALLED  
BEHIND LATH  
AND PLASTER  
MARKED



ROSE WINDOW  
OVER LOBBY AND PART OF ANNEXE

OVER FRONT ENTRY  
DOUBLE DOORS