

Michigan Barn and Farmstead Survey

80-013-400

PROPERTY #
Keith & Pat
 OWNER'S NAME
Eaton
 COUNTY
Skinner-Lur
 COMMON NAME

SURVEYOR _____ DATE _____

BARN

CONDITION

- good
- fair
- poor
- altered
- ruins

ROOF SHAPE

- gable
- gambrel
- gothic
- half monitor
- mansard
- monitor
- ogee
- round
- shed

ROOF COVERING

- asphalt shingle
- slate
- steel: corrugated
- steel: ribbed
- steel: standing seam
- wood shake
- wood shingle
- other: _____

SIDING

- steel
- steel
- wood
- wood
- wood
- wood
- other: _____

FARMHOUSE

CONDITION

- good
- fair
- poor
- altered
- ruins

ROOF SHAPE

- gable
- gambrel
- gothic
- hip
- mansard
- shed
- other: _____

ROOF COVERING

- asphalt shingle
- slate
- steel: corrugated
- steel: ribbed
- steel: standing seam
- tile
- wood shake
- wood shingle
- other: _____

SIDING


- color: White
- aluminum
 - brick
 - concrete block
 - stone
 - vinyl
 - wood: horizontal
 - wood: vertical
 - other: _____

OTHER FEATURES

- cupola
- dormer
- lightning rod
- porch
- weather vane
- other: _____

FOUNDATION MATERIALS

- cement block
- field stone
- field stone – split
- field stone – dressed
- glazed tile
- poured concrete
- other: _____



SKETCH OF FARMSTEAD LAYOUT

